

JEOL JXA-8530F

Electron Probe Micro Analyzer

1) Operator Safety:

- a. Careful when loading/unloading to avoid pinches to hands and fingers.
- b. Do not enter the area behind the system to avoid tripping over cables and damaging system facilities.
- c. Report safety concerns to the NFCF staff through e-mail or by calling 3-8001.

2) Avoiding Machine Damage:

- a. Follow procedures carefully.
- b. Monitor the vacuum status when you load/unload specimen.
- c. Report any system contamination to the NFCF staff.

3) Potential System Hazards:

- a. Pinch Points.
- b. Tripping Hazard.
- c. AC Voltage.
- d. High Voltage.
- e. System Vacuum.

For Emergency Assistance call 412-624-2121. (Internal 4-2121)